
























## KX1/KX2/KX3 's OPTIONAL ACCESSORIES

Specification	Model	KX1	KX2	KX3	Specification	Model	KX1	KX2	KX3
<b>Clamping kit</b>  42 pcs. S/N:10047			✓	✓	<b>Clamping kit</b>  24 pcs. S/N:10105		✓		
<b>Cooling water box</b>  27L S/N:10134		✓	✓	✓	<b>Cutting Tools</b>  S/N:10183		✓	✓	✓
<b>Hand wheel (manual control)</b>  S/N:10186 (SIEG ONLY)		✓	✓	✓	<b>4th axis rotary table</b>  S/N:10185		✓	✓	✓
<b>Mill chuck set</b> MT#3  Chuck dia. 4, 6, 8, 10, 12, 14, 16mm S/N:10037			✓	✓	<b>Mill chuck set</b> MT#2  Chuck dia. 3, 4, 5, 6, 8, 10, mm S/N:10070		✓		
<b>MT#2 collet</b>  ø3mm S/N:10072 ø4mm S/N:10073 ø5mm S/N:10074 ø6mm S/N:10075 ø8mm S/N:10076 ø10mm S/N:10077 ø3-10mm set S/N:10078		✓			<b>Vice with angle</b>  Width 70mm S/N: 10133		✓		
<b>Pcmcia parallel card</b>  S/N:10184 (MACH ONLY)		✓	✓	✓	<b>Vice</b> Width 55mm  S/N: 10108		✓		
<b>2 Fluts Hss end mill</b>  ø3mm S/N:10067 ø4mm S/N:10038 ø5mm S/N:10068 ø6mm S/N:10039 ø8mm S/N:10040 ø10mm S/N:10041 ø3-10mm set S/N:10069		✓			<b>Stand</b>  S/N:10000B		✓		
<b>Computer stand</b>  S/N:10187		✓	✓	✓	<b>Machine stand</b>  S/N:10114B				✓
<b>Quick vice</b>  Width 50mm S/N:10035		✓			<b>Quick vice</b>  Width 100mm S/N:10036			✓	✓

## KC0/KC4/KC6 's OPTIONAL ACCESSORIES

<b>Stand</b>  S/N:10189 (KC4)	<b>Mill chuck set</b>  Chuck dia. 4, 6, 8, 10, 12, 14, 16 mm S/N:10148 (KC4) S/N:10149 (KC6)	<b>Cutter 11 pieces set</b> DIN 4971R DIN 4972R DIN 4973R DIN 4974R DIN 4975 DIN 4976 DIN 4977R DIN 4978R DIN 4980L DIN 4980R DIN 4981R 10x10 mm S/N:10022		<b>Rolling center</b>  MT#2 S/N:10024	<b>Tailstock chuck</b>  Dia.13mm+MT#2 S/N:10027
---	---	---	---	---	---